FIG. 1





FIG. 2



LOW VOLATILIZATION RATE - SHEET SURFACE BECOMES SMOOTH (SHEET) (SHEET) HIGH VOLATILIZATION RATE - SHEET SURFACE BECOMES ROUGH ▼ Dry ► Dry APPLYING DIRECTION OF SHEET APPLYING DIRECTION OF SHEET FIG. 3A HIGH-BOILING POINT/LOW-VAPOR LOW-BOILING POINT/HIGH-VAPOR PRESSURE SOLVENT MEDIUM PRESSURE SOLVENT MEDIUM (COATING MATERIAL) (COATING MATERIAL) Wet — Wet —